[redacted]

201628

INVOICE

PAGE 1

SUNSET IMPORTS

[redacted]

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLACK	18	PORSCHE Panamera	WP0AB2A70JL133816		92525/92528	T9058

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
05MAR18 DD			17:00 18APR25		0.00	CASH	23APR25

R.O. OPENED	READY	OPTIONS:
15APR25	23APR25	

LINE OPCODE TECH TYPE HOURS — LIST — NET — TOTAL

A CUSTOEMR STATES WHERN YOU TURN VEHICLE ON WILL HEAR THE SPORT EXHAUST IS MAKING A SQUEEK/FLAPPING NOISE. ADVISOR HEARD IN DRIVE. PLEASE INSPECT

01 REPAIR

90764 WP (N/C)

1 971-253-607 REAR SILENCER (N/C)

1 SHIP EXPEDITED SHIPPING (N/C)

1 PAB-111-220-A CLAMPING SLEEVE (N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

92528 Verified concern, started vehicle and switch to sport mode and could hear driver's side exhaust flap cycling repeatedly. Performed VAL, found fault P04A000 - Exhaust flap, bank 2 - signal implausible. Lifted vehicle to insnpect further and found excessive play in flap mechanism inside left muffler. Recommend replacing left muffler assembly. --- Replaced left muffler and performed exhaust flap adaptation procedure. Cleared faults and road tested vehicle. Performed VAL, no faults returned.

****

B CUSTOMER STATES DRIVER SIDE WINDOW MAIN SWITCH/ BUTTON FOR DRIVER'S WINDOW INTERMITTENTLY WILL NOT WORK CORRECTLY, YOU MUST PRESS MULTIPLE TIMES FOR IT TO WORK. PLEASE INSPECT

01 REPAIR

90764 WP (N/C)

1 971-959-858-C-HUO SWITCH FOR ELECTRIC WINDOW REGULATOR HIG (N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

92528 Verified concern, found driver's window switch intermittently not working. No faults. Recommend replacing window switch assembly. -- Removed left front door panel. Removed and replaced window switch assembly. Reassembled door and performed window stop adaptation. Window switch working normally now.

****

C CUSTOMER STATES CAR PLAY IS NOT WORKING PROPERLY WHEN CONNECTING CABLE IT IS NOT AUTOMATICALY CONNECTING

CUSTOMER COPY

STATEMENT OF DISCLAIMER

Any warranties on the parts and/or accessories sold hereby are those made by the manufacturer. The seller, SUNSET IMPORTS, hereby expressly disclaims all warranties either express or implied, including all implied warranties of merchantability or fitness for a particular purpose, and SUNSET IMPORTS neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of these parts and/or accessories.

ALL REPAIRS ARE WARRANTIED FOR 24 MONTHS, EXCLUDING BATTERIES AND TIRES.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
SHOP SUPPLIES	
TOTAL CHARGES	
LESS INSURANCE	
MISC. CHARGES	
PLEASE PAY THIS AMOUNT	

Copyright 2015 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

CUSTOMER COPY

[redacted]

201628

INVOICE

PAGE 2

SUNSET IMPORTS

[redacted]

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLACK	18	PORSCHE Panamera	WP0AB2A70JL133816		92525/92528	T9058

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
05MAR18 DD			17:00 18APR25		0.00	CASH	23APR25

R.O. OPENED	READY	OPTIONS:
15APR25	23APR25	

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
01 REPAIR			
90764 WP			(N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C:			0.00
92528 Tested with iphone 16 and new apple brand usb cable and connection works right away on every attempt. Found client is using aftermarket usb cable. Could potentially be causing issue.			
**********			
D 0200 CLIENT STATES THAT VEHICLE WILL SHAKE AT 60 - 62 MPH AND WOULD LIKE TIRES BALANCED			
90 INSTRUMENTS			
90764 CPT		0.00	0.00
1 955-361-957-10-057 1 SET WHEEL STUDS, ANTI-THEFT WHEEL BOLT	38.69	38.69	38.69
PARTS: 38.69 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D:			38.69
92528 Road tested vehicle and verified concern. Road force balanced front wheels. Attempted rears, but found both rear wheels are bent and unable to be balanced. Recommend replacing left and right rear wheels			
**********			
E CUSTOMER HAS CPO WARRANTY			
NOTE GENERAL INFORMATION			
90764 CP		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E:			0.00
**********			
F PERFORM PORSCHE MULT-POINT INSPECTION REPORT WITH TECHNICIAN WALK AROUND VIDEO.			
MPI PERFORM PORSCHE MULT-POINT INSPECTION REPORT WITH TECHNICIAN WALK AROUND VIDEO.			
90764 CP		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE F:			0.00
**********			
G 2-3 BUSINESS DAYS DIAG.			
CAUSE: INPUT TIME FRAME QUOTED, PARTS ARRIVAL TIME AS APPLICABLE, AND FIRST COMMUNICATION SCHEDULED.			
TIMEFRAME INPUT TIME FRAME QUOTED, PARTS ARRIVAL			

CUSTOMER COPY

STATEMENT OF DISCLAIMER

Any warranties on the parts and/or accessories sold hereby are those made by the manufacturer. The seller, SUNSET IMPORTS, hereby expressly disclaims all warranties either express or implied, including all implied warranties of merchantability or fitness for a particular purpose, and SUNSET IMPORTS neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of these parts and/or accessories.

ALL REPAIRS ARE WARRANTIED FOR 24 MONTHS, EXCLUDING BATTERIES AND TIRES.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
SHOP SUPPLIES	
TOTAL CHARGES	
LESS INSURANCE	
MISC. CHARGES	
PLEASE PAY THIS AMOUNT	

Copyright 2015 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

CUSTOMER COPY

[redacted]

201628

INVOICE

PAGE 3

SUNSET IMPORTS

[redacted]

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLACK	18	PORSCHE Panamera	WP0AB2A70JL133816		92525/92528	T9058

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
05MAR18 DD			17:00 18APR25		0.00	CASH	23APR25

R.O. OPENED	READY	OPTIONS:
15APR25	23APR25	

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
TIME AS APPLICABLE, AND FIRST COMMUNICATION SCHEDULED.			
90764 CP		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE G:			0.00
**********			
H COMPLIMENTARY EXTERIOR WASH.			
FW COMPLIMENTARY EXTERIOR WASH.			
90764 CP		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE H:			0.00
**********			
I PROVIDE COMPLIMENTARY SHUTTLE VIA UBER TRANSPORTATION SERVICES			
UBER PROVIDE COMPLIMENTARY SHUTTLE VIA UBER TRANSPORTATION SERVICES			
90764 CP		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE I:			0.00
**********			

****

ESTIMATE: 190.00 15APR25 17:50 SA: 90871

CONTACT:

****

CUSTOMER COPY

STATEMENT OF DISCLAIMER

Any warranties on the parts and/or accessories sold hereby are those made by the manufacturer. The seller, SUNSET IMPORTS, hereby expressly disclaims all warranties either express or implied, including all implied warranties of merchantability or fitness for a particular purpose, and SUNSET IMPORTS neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of these parts and/or accessories.

ALL REPAIRS ARE WARRANTIED FOR 24 MONTHS, EXCLUDING BATTERIES AND TIRES.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	38.69
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
SHOP SUPPLIES	0.00
TOTAL CHARGES	38.69
LESS INSURANCE	0.00
MISC. CHARGES	0.15
PLEASE PAY THIS AMOUNT	38.84

Copyright 2015 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

CUSTOMER COPY

[redacted]

194204

INVOICE

PAGE 1

SUNSET IMPORTS

[redacted]

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLACK	18	PORSCHE Panamera	WP0AB2A70JL133816		91723/91726	T6063

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
05MAR18 DD			WAIT 23JUL24		0.00	CASH	23JUL24

R.O. OPENED	READY	OPTIONS:
23JUL24	23JUL24	

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A PERFORM PORSCHE MULT-POINT INSPECTION REPORT WITH TECHNICIAN WALK AROUND VIDEO.			
MPI PERFORM PORSCHE MULT-POINT INSPECTION REPORT WITH TECHNICIAN WALK AROUND VIDEO.			
90965 CP	0.00	0.00	
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A:			0.00
91726 MPI Performed Porsche multi point inspection. Inspected condition and topped off all fluids as necessary. Verified proper operation of horn and all exterior lighting. Inspected headlamps for proper adjustment. Inspected condition of windshield wipers. Verified proper operation of HVAC system. Inspected for any signs of fluid leakage and noted any concerns. Inspected condition of CV axles and boots. Inspected condition of operation of exhaust system. Checked for excessive wear or damage to all visible steering and suspension components. Checked condition of drive belt. Performed road test to inspect proper operation of brakes, transmission, and handling characteristics. Front brake pads measure 7mm. Rear brake pads measure 5mm. Front tires measure 8mm. Rear tires measure 6mm. Performed battery state of charge test: 72%. Checked service history. See MK for more details.			
**********			
B GUEST RECENTLY PURCHASED VEHICLE REQUESTS INSPECTION			
NOTE GENERAL INFORMATION			
99 CP	0.00	0.00	
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B:			0.00
**********			
C TECHNOLOGIST TO HELP ANSWER QUESTIONS			
NOTE GENERAL INFORMATION			
99 CP	0.00	0.00	
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C:			0.00
**********			
D ***PLEASE DO NOT WASH VEHICLE***			
DNW ***PLEASE DO NOT WASH VEHICLE***			
99 CP	0.00	0.00	

CUSTOMER COPY

STATEMENT OF DISCLAIMER

Any warranties on the parts and/or accessories sold hereby are those made by the manufacturer. The seller, SUNSET IMPORTS, hereby expressly disclaims all warranties either express or implied, including all implied warranties of merchantability or fitness for a particular purpose, and SUNSET IMPORTS neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of these parts and/or accessories.

ALL REPAIRS ARE WARRANTIED FOR 24 MONTHS, EXCLUDING BATTERIES AND TIRES.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
SHOP SUPPLIES	
TOTAL CHARGES	
LESS INSURANCE	
MISC. CHARGES	
PLEASE PAY THIS AMOUNT	

Copyright 2015 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

CUSTOMER COPY

[redacted]

194204

INVOICE

PAGE 2

[redacted]

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLACK	18	PORSCHE Panamera	WP0AB2A70JL133816		91723/91726	T6063

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
05MAR18 DD			WAIT 23JUL24		0.00	CASH	23JUL24

R.O. OPENED	READY	OPTIONS:
23JUL24	23JUL24	

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

****

E CLIENT WILL BE WAITING FOR SERVICE. CLIENT QUOTED 2-3 HOURS FOR SERVICE.
WAIT CLIENT WILL BE WAITING FOR SERVICE. CLIENT QUOTED X HOURS FOR SERVICE.
99 CP 0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00

****

F** CLIENT REQUESTS LABOR ESTIMATE TO REPLACE SUPPLIED LEFT REAR SEATBELT.
50 BODY - FRONT
90965 CP 0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE F: 0.00

****

G** CLIENT REQUESTS LABOR ESTIMATE TO REPLACE SUPPLIED REAR SUNSHADE SWITCH ASSEMBLY.
50 BODY - FRONT
90965 CP 0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE G: 0.00

****

CUSTOMER COPY

STATEMENT OF DISCLAIMER

Any warranties on the parts and/or accessories sold hereby are those made by the manufacturer. The seller, SUNSET IMPORTS, hereby expressly disclaims all warranties either express or implied, including all implied warranties of merchantability or fitness for a particular purpose, and SUNSET IMPORTS neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of these parts and/or accessories.

ALL REPAIRS ARE WARRANTIED FOR 24 MONTHS, EXCLUDING BATTERIES AND TIRES.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
SHOP SUPPLIES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
MISC. CHARGES	0.00
PLEASE PAY THIS AMOUNT	0.00

Copyright 2015 CDK Global, LLC SERVICE INVOICE TYPE 2 - SI2C - IMAGING

CUSTOMER COPY